## TITLE 6: BUILDING REGULATIONS DIVISION 3: BUILDING REGULATIONS Chapter 11: DISASTER RECONSTRUCTION. Sections

63.111	Intent.
63.115	Invocation of Provisions.
63.1110	Definitions.
63.1115	Repair Criteria.
63.1120	Historic Buildings.
63.1125	Chimneys.
63.1130	Unreinforced Masonry.
63.1135	Essential Service Facilities
63.1140	Board of Appeals.

### 63.111 Intent.

This chapter establishes regulations for adequate and expeditious repair and reconstruction of structures damaged as a result of a disaster for which a local emergency has been declared by the Board of Supervisors. The chapter does not allow exemptions from the Building, Fire or other codes.

Adopted Ordinance #3501 (1992);

### 63.115 Invocation of Provisions.

The provisions of this chapter are applicable following each disaster for which a local emergency has been declared by the Board of Supervisors. The Board may extend the provisions as necessary.

Adopted Ordinance #3501 (1992):

#### 63.1110 Definitions.

For the purposes of this chapter the following definitions apply:

- (a) "Current code" shall mean the edition of the Uniform Building Code, published by the International Conference of Building Officials, as adopted by the County of San Bernardino in accordance with operation of law pursuant Health and Safety Code §18941.5.
- (b) "Essential Service Facilities" shall mean those structures which are necessary for emergency operations subsequent to a disaster.

Adopted Ordinance #3501 (1992);

## 63.1115 Repair Criteria.

Damaged structures of all occupancies regulated by the County of San Bernardino which have been damaged as a result of a disaster shall be repaired in accordance with the following criteria:

- (a) When the estimated value of repair does not exceed ten percent (10%) of the replacement value of the structure, the damaged portion(s) shall be restored to their predisaster condition.
- (b) When the estimated value of repair is greater than ten percent (10%), but less than fifty percent (50%), of the replacement value of the structure, the damaged elements, as well as all critical ties associated with those elements, shall be repaired and/or brought into conformance with the structural requirements of the current code.
- (c) When the estimated value of repair exceeds fifty percent (50%) of the replacement value of the structure, the entire structure shall be brought into conformance with the structural requirements of the current code.
- (d) EXCEPTION: The repair of damaged chimneys in Group R, Division 3 occupancies shall be excluded from the computation of percentage of replacement value and chimneys shall be repaired pursuant to §63.1125.

Adopted Ordinance #3501 (1992);

# 63.1120 Historic Buildings.

All damaged buildings or structures currently considered as historic places, or qualifying structures within established historic districts, shall be repaired in accordance with the standards in §63.1115, above, with due consideration given to the historical ratings. Additional standards and criteria, as noted in the State of California

Historic Building Code, shall apply. Where conflicts occur between these standards and the State of California Historic Building Code, the standards in §63.1115 still govern.

Adopted Ordinance #3501 (1992);

### 63.1125 Chimneys.

All damaged chimneys must be evaluated by a State of California registered civil or structural engineer or licensed architect prior to reconstruction and shall be constructed in accordance with Chapter 37 of the current code. Unconventional masonry fireplace and chimney systems may be constructed pursuant to the alternate materials and methods of construction provisions of the current code. Further, all new or reconstructed chimneys shall be anchored to the structure in accordance with the current code. Where the portion or the chimney extending above the roof line exceeds two times the least dimension of the chimney, the portion extending above the roof line shall be braced to the roof structure.

Adopted Ordinance #3501 (1992);

### 63.1130 Unreinforced Masonry.

All damaged buildings determined to be constructed of unreinforced masonry shall be repaired and strengthened to comply with the currently adopted edition of the Uniform Code for Building Conservation, Appendix Chapter I.

Adopted Ordinance #3501 (1992);

### 63.1135 Essential Service Facilities.

Damaged structures of all occupancies regulated by the County of San Bernardino which have been damaged as a result of a disaster which are Essential Service Facilities shall be repaired in accordance with the following criteria:

- (a) When the estimated value of repair does not exceed fifty percent (50%) of the replacement value of the structure, the damaged elements, as well as all critical ties associated with those elements, shall be repaired and/or brought into conformance with the structural requirements of the current code.
- (b) When the estimated value of repair exceeds fifty percent (50%) of the replacement value of the structure, the entire structure shall be brought into conformance with the structural requirements of the current code.

Adopted Ordinance #3501 (1992);

## 63.1140 Board of Appeals.

In order to determine the suitability of alternate materials and methods of construction and to provide for reasonable interpretation of this Chapter, all technical decisions allowed by this Chapter may be appealed to the San Bernardino County Board of Appeal pursuant to San Bernardino County Code §63.012.

Adopted Ordinance #3501 (1992);